


| BUILDING ID                                                                                                                                                                                                                | LOCATION     |          |              | SAMPLE TAKEN |     | SUSPECTED |    | PRODUCT TYPE | CONDITION | PRIORITY |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------|----------|--------------|--------------|-----|-----------|----|--------------|-----------|----------|
|                                                                                                                                                                                                                            | Elevation    | Locality | Position     | Yes/No       | No. | Yes       | No |              |           |          |
| Lower Primary                                                                                                                                                                                                              | Ground level | External | Cover strips | Yes          | 77  |           |    | Fibre Cement | Average   | 4        |
| <div>Notes: </div> <div>* <u>Cover strips</u> to external wall sheeting of the building - <b><i>No Asbestos fibre detected.</i></b></div> |              |          |              |              |     |           |    |              |           |          |
| Lower Primary                                                                                                                                                                                                              | Ground level | External | Walls        | Yes          | 78  |           |    | Fibre Cement | Average   | 4        |