

BUILDING ID	LOCATION			SAMPLE TAKEN		SUSPECTED		PRODUCT TYPE	CONDITION	PRIORITY
	Elevation	Locality	Position	Yes/No	No.	Yes	No			
Pool Shed	Ground level	External	Eaves	Yes	30	Yes		Asbestos Cement	Average	4
<i>Notes:</i> * <u>Eaves</u> lining to the Pool Shed - Chrysotile Asbestos fibre detected. NOT FOUND 10/04/2024										
Florence House	Ground level	Internal	Floor	Yes	31			Vinyl tiles	Average	4
<i>Notes:</i> * <u>Vinyl</u> tiles to the Laundry floor – No Asbestos fibre detected. For 2024 Re-inspected										
Florence House	Ground level	Internal	Wall	Yes	32	Yes		Asbestos Cement	Average	4
<i>Notes:</i> * <u>Internal</u> wall sheeting to the Laundry - Chrysotile Asbestos fibre detected.										
Florence House	Ground level	Internal	Wall	No		Yes		Asbestos Cement	Average	4
<i>Notes:</i> * <u>Internal</u> wall sheeting to the shower room and side entry of the Residence along with the bathroom to the Residential Flat is suspected to contain Asbestos fibre.										
Florence House	Ground level	Internal	Ceiling	No		Yes		Asbestos Cement	Average	4
<i>Notes:</i> * <u>Ceiling</u> sheeting to the shower & toilet rooms, laundry and side entry of the Residence along with the bathroom to the Flat is suspected to contain Asbestos fibre.										
Florence House	Ground level	External	Wall	Yes	33	Yes		Asbestos Cement	Average	4
<i>Notes:</i> * <u>External</u> profiled wall sheeting to the Residence - Chrysotile Asbestos fibre detected.										
Florence House	Ground level	External	Wall	Yes	34	Yes		Asbestos Cement	Average	4
<i>Notes:</i> * <u>External</u> profiled wall sheeting to the Residential Flat - Chrysotile Asbestos fibre detected.										