


BUILDING ID	LOCATION			SAMPLE TAKEN		SUSPECTED		PRODUCT TYPE	CONDITION	PRIORITY
	Elevation	Locality	Position	Yes/No	No.	Yes	No			
Humanities	Lower level	Internal	Fuse board	Yes	72	Yes		<u>Zelemite</u>	Average	4
Notes: <u>* Black backing board to the fuse board beneath the building - Chrysotile Asbestos fibre detected HEALTH CARE CENTER + DAY CARE CENTER - NOT FOUND 10/04/2024</u>										
Humanities	Lower level	External	Wall	No		Yes		Asbestos cement	Average	4
Notes: <u>* External wall sheeting to the lower level of the building is suspected to contain Asbestos fibre.</u> A/C SHEET FOUND - GARAGE AREA										
Humanities	Upper level	Internal	Floor	Yes	73	Yes		Vinyl	Poor	1
Notes: <u>* Vinyl flooring to the Kitchen area adjacent the Bathroom in Health Centre - Chrysotile Asbestos fibre detected</u> HEALTH CARE CENTER + DAY CARE CENTER - NOT FOUND 10/04/2024										
Humanities	Upper level	Internal	Wall	Yes	74	Yes		Asbestos Cement	Average	4
Notes:  <u>* Internal wall sheeting to Kitchen of Health Centre, common to other walls - Chrysotile Asbestos fibre detected</u> FOUND 10/04/2024										
Humanities	Upper level	Internal	Ceiling	Yes	75	Yes		Asbestos cement	Average	4